











REPORT No.: SZ24090048W09





















REPORT No.: SZ24090048W09







REPORT No.: SZ24090048W09




2A-4A / 20+10MHz / QPSK / Mid+Mid CH /
1@0-1@492A-4A / 20+10MHz / QPSK / Mid+Mid CH /
1@99-1@02A-4A / 20+10MHz / QPSK / Mid+Mid CH /
100@0-50@02A-4A / 20+10MHz / QPSK / Mid+High CH /
1@0-1@492A-4A / 20+10MHz / QPSK / Mid+High CH /
1@99-1@02A-4A / 20+10MHz / QPSK / Mid+High CH /
100@0-50@0






2A-4A / 20+10MHz / QPSK / High+High CH /
1@0-1@49




2A-4A / 20+10MHz / QPSK / High+High CH /
1@99-1@0









2A-4A / 20+10MHz / QPSK / High+High CH /
100@0-50@0

N/A





REPORT No.: SZ24090048W09


2A-12A / 20+10MHz / QPSK / Low+High CH /
1@0-1@492A-12A / 20+10MHz / QPSK / Low+High CH /
1@99-1@02A-12A / 20+10MHz / QPSK / Low+High CH /
100@0-50@02A-12A / 20+10MHz / QPSK / Mid+Low CH /
1@0-1@492A-12A / 20+10MHz / QPSK / Mid+Low CH /
1@99-1@02A-12A / 20+10MHz / QPSK / Mid+Low CH /
100@0-50@0Shenzhen Morlab Communications Technology Co., Ltd.
FL.1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555

Http://www.morlab.cn


Fax: 86-755-36698525

E-mail: service@morlab.cn







2A-12A / 20+10MHz / QPSK / High+Low CH /
1@0-1@49




2A-12A / 20+10MHz / QPSK / High+Low CH /
1@99-1@0




2A-12A / 20+10MHz / QPSK / High+Low CH /
100@0-50@0



2A-12A / 20+10MHz / QPSK / High+Mid CH /
1@0-1@49



2A-12A / 20+10MHz / QPSK / High+Mid CH /
1@99-1@0



2A-12A / 20+10MHz / QPSK / High+Mid CH /
100@0-50@0