











## TROUBLESHOOTING 1. The headset cannot be connected to the bluetooth device © Confirm the status of the Bluetooth function; Turn off bluetooth function of your device, delete the historical connection

How to fix it: Replace a new charging cable.

How to fix it:

4. The headset have no sound How to fix it:

(1) Check whether the audio track is played via the smartphone application.

Check the headset battery whether was run out of.
 Increase the volume of headset and mobile devices (or music playback)

Turn off the headset and turn on it again, then try to connect with your

-8-

 Make sure that the correct mobile device is connected (5) Please try to connect to other mobile devices

FCC STATEMENT

This device complies with Part 15 of the FCC Rules. Operation is subject to

the following two conditions:
(1) This device may not cause harmful interference, and

(2) This device must accept any interference received, including interference that may cause undesired operation.

⚠ Warning:

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on the user is encouraged to try to correct the interference by one off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

(1)Reorient or relocate the receiving antenna.

(2)Increase the separation between the equipment and receiver.Connect the equipment into an outlet on a circuit different from that to which the

receiver is connected.

(3)Consult the dealer or an experienced radio/TV technician for help.

The device has been evaluated to meet general RF exposure requirement. The device can be used in portable exposure condition without restriction.

-9-

**Warning** 

Do not place device in very low or high temperature envi-ronment, in extreme temperature environment, headset may transform, battery capacity may decrease, headset lifetime may be shorten.

2.Do not use headset in storm, The headset may be broken and will increase the risk of lightening stroke.

3.Do not disassemble or refit the headset for any reason, it make broken of the

headset.Please send it to sales agency to repair. 4.Repeated charging and discharging will make the battery performance reduced after sometime, this is normal for all rechargeable batteries.

by kids or pets to avoid any unexpected accidents.

No matter the product is lost, outdated, broken or you just don't like this product, please contact our customer service, we will do our best to give

## PRODUCT FEATURE

Model:	BH830
Bluetooth version:	V5.1
Working distance:	33~50 feets
Earbuds charging time:	1.5Hrs
Standby time:	about 120Hrs
Charging input:	DC5.0V/1A
Capacity of headset:	150mAh
Support:	IOS/Andriod/Laptop
Functions:	Music/voice prompt/phone call
Music time:	25Hrs
Ta <b>j</b> k time:	22Hrs
Weight of single headset:	17g

- 11 -

EC REP C&E Connection E-Commerce (DE) GmbH Zum Linnegraben 20, 65933, Frankfurt am Main, Germany

> FC (E of the second Made in China

- 10 -