






FCC ID:2AVH4DLZYROBOT15422



## Internal Photos



### 1. EUT uncover view


















































































































































































































































## 2. Antenna view



Note: CDMA and LTE functions have been turned off from the software. Users cannot use this function.



