



S/N 16 T 0388861 03/21

Firmware: 7.50.31

BLK 100

Key Fob Reader

Electr. Ratings: 8 to 16 V DC, 0.2 A

FCC ID: 2AVM3BLK100

IC: 25831-BLK100

HVIN: BLK100E5.1

ALS P/N: 205135

wh Münzprüfer
Dietmar Trenner GmbH
Teltower Damm 276
D-14167 Berlin
www.whberlin.de

MADE IN GERMANY

