

C.O.B.O. SPA  
Via Tito Speri, 10  
Leno (BS), Italy

## Model Differences Letter

The DBS Immobilizer family of products identified with the FCC ID: 2AVOV-04610339 and the IC: 25864-04610339 (HVIN: 04610339) is composed by the following models:

**04610339, 04610339 vrs 2, 04610339 vrs 3**  
**04610365**

The only difference between 04610339 and 04610365 is the SW.

The differences between 04610339 and 04610339 vrs 2 are the CS due to the substitution of two components (LP8867C-Q1 Low EMI Automotive LED Driver and DRV8873-Q1 Automotive H-Bridge Motor Driver) and the presence of a thread.

The differences between 04610339 vrs 2 and 04610339 vrs 3 are the CS and the absence of the thread.

These changes had no impact on the RF section.

Sincerely,

Signed: 

Date: 10/13/2022

Printed name: Wolfgang Cozzi

Title: President

Company Name: C.O.B.O. Spa