

# INTERTEK TESTING SERVICE


Report No: HK23051484

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

(Front View)

**Powered by Notebook USB Port + 2.4GHz Operating**



# INTERTEK TESTING SERVICE


Report No: HK23051484

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

(Rear View)

Powered by Notebook USB Port + 2.4GHz Operating



# INTERTEK TESTING SERVICE

Report No: HK23051484

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

**(Side View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# INTERTEK TESTING SERVICE

---

Report No: HK23051484

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

(Front View)

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# INTERTEK TESTING SERVICE

---


Report No: HK23051484

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

(Rear View)

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# INTERTEK TESTING SERVICE

Report No: HK23051484

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

**(Side View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**

