

---

## INTERTEK TESTING SERVICE

---

Report No: HK23051484

### Configuration Photographs

#### Worst-Case Radiated Emissions

(Front View)

Powered by Internal 3.7V rechargeable battery + 2.4GHz Operating



## **INTERTEK TESTING SERVICE**

---


Report No: HK23051484

### **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Internal 3.7V rechargeable battery + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---

Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Internal 3.7V rechargeable battery + 2.4GHz Operating**



## **INTERTEK TESTING SERVICE**

---


Report No: HK23051484

### **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Internal 3.7V rechargeable battery + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---

Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---


Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---

Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



## **INTERTEK TESTING SERVICE**

---


Report No: HK23051484

### **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating**





# **INTERTEK TESTING SERVICE**

---


Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# **INTERTEK TESTING SERVICE**

---

Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# **INTERTEK TESTING SERVICE**

---

Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# **INTERTEK TESTING SERVICE**

---

Report No: HK23051484

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**

