

INTERTEK TESTING SERVICE


Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Base Station wifi and Bluetooth BLE Operating with Charging Sensor



INTERTEK TESTING SERVICE


Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Base Station wifi and Bluetooth BLE Operating with Charging Sensor



INTERTEK TESTING SERVICE


Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Base Station wifi and Bluetooth BLE Operating with Charging Sensor



INTERTEK TESTING SERVICE


Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Base Station wifi and Bluetooth BLE Operating with Charging Sensor



INTERTEK TESTING SERVICE


Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Base Station wifi and Bluetooth BLE Operating



INTERTEK TESTING SERVICE


Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Base Station wifi and Bluetooth BLE Operating




Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Base Station wifi and Bluetooth BLE Operating



INTERTEK TESTING SERVICE

Report No: HK21081567

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Base Station wifi and Bluetooth BLE Operating

