







11N40SISO_Ant1_Low_5755




11N40SISO_Ant1_Low_5755







11N40SISO_Ant2_Low_5755




11N40SISO_Ant2_Low_5755





11N40SISO_Ant2_Low_5755





11N40SISO_Ant1_High_5795

















11AC20SISO_Ant1_Low_5745





11AC20SISO_Ant2_Low_5745














11AC20SISO_Ant2_High_5825




11AC20SISO_Ant2_High_5825








11AC40SISO_Ant1_Low_5755




11AC40SISO_Ant1_Low_5755









11AC40SISO_Ant1_High_5795




11AC40SISO_Ant1_High_5795



SGS-CSTC Standards Technical Services Co., Ltd.
Guangzhou Branch


Page: 298 of 496
Report No.: GZCR210502031703
FCC ID: 2AWD4-ECHTES101




11AC40SISO_Ant1_High_5795




11AC40SISO_Ant2_High_5795







11AC40SISO_Ant2_High_5795




11AC80SISO_Ant1_Low_5775




11AC80SISO_Ant1_Low_5775




11AC80SISO_Ant1_Low_5775



11AC80SISO_Ant1_Low_5775



11AC80SISO_Ant1_High_5775







11AC80SISO_Ant1_High_5775




11AC80SISO_Ant2_Low_5775




11AC80SISO_Ant2_Low_5775




11AC80SISO_Ant2_Low_5775



11AC80SISO_Ant2_Low_5775



11AC80SISO_Ant2_High_5775



11AC80SISO_Ant2_High_5775

11AC80SISO_Ant2_High_5775