

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFT
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+

External Photographs



Figure 1. EUT and Accessories

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 2. Top View


US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFT
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 3. Side 1

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFT
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 5. Side 3

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 6. Side 4

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 7. Bottom View