

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+

Test Configuration Photographs



Figure 1. EUT on Test Table

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+




Figure 2. Radiated Emissions Test Configuration (below 30 MHz)

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+




Figure 2. Radiated Emissions Test Configuration (30 - 200 MHz)

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 4. Radiated Emissions Test Configuration (200 - 1000 MHz)

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 3. Radiated Emissions Test Configuration (above 1000 MHz, Unintentional Emissions)

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AXLF-SHIFTP
20-0242
December 4, 2020
FAAFTECH TECNOLOGIA LTDA
SP(NN)+



Figure 4. Radiated Emissions Test Configuration (above 1000 MHz, Intentional Emissions)