



Operating Instructions for Smart Sport Watch Product



3. The reminder switch is turned on, but there is no reminder on the watch, or the reminder is sporadic.
- If the phone turns on the notification dialog and the companion app is not running according to the above tips, the Bluetooth is kept on, and the APN and the watch are kept connected. If the phone is connected to the watch but the watch is not working, the user needs to check the message push function.
4. An Android phone (phone often disconnects or has no message push function).
- Android will turn time to clean up the phone's background applications or applications that consume more power, so the phone will be unable to connect to the watch. If the phone is easily cleaned and the connection with the Bluetooth will drop off. Different phones have different ways to clean up background running settings. As in the Huawei Honor 8 IT Settings - Battery Management. Timely manage to turn on or background running.
5. An iPhone (phone often disconnects or has no message push function).
- Support for 24 months for replaced, defective, upgraded or major software update. Please write to us via email below within 10 days. yeter357@gmail.com

Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) that this device does not cause harmful interference, and (2) that this device accept any interference, including interference that may cause undesired operation of the equipment. The FCC ID assigned to this equipment is 2ABDQ-A1000. The equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:
- Reorienting or relocating the receiving antenna.
- Increasing the separation between the equipment and receiver.
- Connecting the equipment into a circuit different from that to which the receiver is connected.
- Consulting an authorized radio/TV technician for help.

IC Warning
The device contains a battery. Canada's silence-exempt RSS standard. Operation in quiet areas may cause two conditions:
(1) This device may not cause interference and
(2) This device may accept interference, including interference that may cause unwanted operation of the device.
This device complies with RSS-240, license by Industry Canada. So it complies with two conditions suivants:
(1) Ce dispositif ne peut causer d'interférence; et
(2) Ce dispositif doit accepter toute interférence, y compris les interférences qui peuvent causer un mauvais fonctionnement de l'appareil.
This Class B digital apparatus complies with Canadian ICES-003.
Get a report n° 1008 à la CRTC et il est conforme à la norme NMB-003 du Canada.
The device has been evaluated to meet IC exposure requirement.
The device can be used in people exposure condition without restriction.
D'après les tests, il n'est pas recommandé pour les personnes enceintes et il est dû à éviter d'exposer RF.
L'appareil peut être utilisé sans restriction dans les conditions d'exposition portables.

Learning