

# Shenzhen Tongwei Electronics Co. Ltd

May. 25, 2021

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2AZ38KA-TB01

There are no external tuning adjustments, The amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Wenjuan Yu 

Manager