





SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.


Report No.: SHCR240300044202



11AC20MIMO_Ant1_5220



11AC20MIMO_Ant2_5220







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC20MIMO_Ant1_5240



11AC20MIMO_Ant2_5240




11AC20MIMO_Ant1_5260




SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202






11AC20MIMO_Ant2_5300



11AC20MIMO_Ant1_5320




11AC20MIMO_Ant2_5320



SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC20MIMO_Ant1_5580



11AC20MIMO_Ant2_5580




11AC20MIMO_Ant1_5700




SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.


Report No.: SHCR240300044202



11AC20MIMO_Ant2_5700



11AC20MIMO_Ant1_5745







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC20MIMO_Ant2_5745



11AC20MIMO_Ant1_5785




11AC20MIMO_Ant2_5785




SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202






11AC40MIMO_Ant1_5190



11AC40MIMO_Ant2_5190




11AC40MIMO_Ant1_5230




SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.


Report No.: SHCR240300044202



11AC40MIMO_Ant2_5230



11AC40MIMO_Ant1_5270







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC40MIMO_Ant2_5270



11AC40MIMO_Ant1_5310




11AC40MIMO_Ant2_5310



SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC40MIMO_Ant1_5590



11AC40MIMO_Ant2_5590




11AC40MIMO_Ant1_5670



SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.


Report No.: SHCR240300044202



11AC40MIMO_Ant2_5670




11AC40MIMO_Ant1_5755






11AC40MIMO_Ant2_5755



11AC40MIMO_Ant1_5795




11AC40MIMO_Ant2_5795




SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.


Report No.: SHCR240300044202



11AC80MIMO_Ant1_5210



11AC80MIMO_Ant2_5210







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC80MIMO_Ant1_5290



11AC80MIMO_Ant2_5290




11AC80MIMO_Ant1_5530



SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202







SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Report No.: SHCR240300044202

11AC80MIMO_Ant2_5610



11AC80MIMO_Ant1_5775



11AC80MIMO_Ant2_5775

