



5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:31:54

5MHz_Low_QPSK_25@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:32:08

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:32:22

5MHz_Middle_QPSK_25@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:32:35

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:32:47

5MHz_High_QPSK_25@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:33:00

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:33:50

10MHz_Low_QPSK_50@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:34:03

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:34:16

10MHz_Middle_QPSK_50@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:34:29

10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:34:42

10MHz_High_QPSK_50@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:34:55


LTE Band 17, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Low_QPSK_25@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_25@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)



5MHz_High_QPSK_25@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:37:26

10MHz_Low_QPSK_50@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:37:39

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:37:52

10MHz_Middle_QPSK_50@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:38:06

10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:38:23

10MHz_High_QPSK_50@0(30MHz~8.16GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 10:38:37


LTE Band 41, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




5MHz_Low_QPSK_25@0(30MHz~27.9GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




5MHz_Middle_QPSK_25@0(30MHz~27.9GHz)




5MHz_High_QPSK_1@0(30MHz~27.9GHz)



5MHz_High_QPSK_25@0(30MHz~27.9GHz)




10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:22:07

10MHz_Low_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:22:29

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:22:52

10MHz_Middle_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:23:15

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:23:37

10MHz_High_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:24:00

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:25:07

15MHz_Low_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:25:28

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:25:50

15MHz_Middle_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:26:12

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:26:36

15MHz_High_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:27:01

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:28:08

20MHz_Low_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:28:33

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:28:55

20MHz_Middle_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:29:18

20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:29:41

20MHz_High_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21.JUL.2025 11:30:04


LTE Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Low_QPSK_6@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_6@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)



1.4MHz_High_QPSK_6@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:52:33

3MHz_Low_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:53:05

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:53:38

3MHz_Middle_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:54:08

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:54:40

3MHz_High_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:55:11

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:56:20

5MHz_Low_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:56:52

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:57:23

5MHz_Middle_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:57:57

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:58:28

5MHz_High_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 15:58:01

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 16:00:16

10MHz_Low_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 16:00:48

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 16:01:20

10MHz_Middle_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 16:01:52

10MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 16:02:25

10MHz_High_QPSK_50@0(30MHz~18.8GHz)



ProjectNo.:RKSA250707003 Tester:Jason Lu
Date: 21 JUL 2025 16:02:57