


FCC certification No. Cover Letter

We, Yeasound (Xiamen) Hearing Technology Co., Ltd, hereby submit justification for placing the FCC certification No. in the associated user's manual and packaging.

According to the FCC regulation, the FCC certification No. should be printed on the dongle, but as the dongle are too small to print the label (**FCC ID: 2BFVL-RIC800**), it will be moved to the user manual and packaging. The details are as below:

- A. Side surface (A): The side surface does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.
- B. Top cover (B): The top cover does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.




Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the user's manual and packaging.

Yeastound (Xiamen) Hearing Technology Co., Ltd
No.668 Hu'an Road, Huli District, Xiamen China
Tel: +86 0592-5702000-3099
Email: zenghuoling@yeasound.com

Label:

FCC ID: 2BFVL-RIC800



Stick the label on package and page 85 of user manual.

Best regards,

Signature:

A handwritten signature in black ink that reads "Alina Zeng". The signature is written in a cursive, flowing style.

Alina Zeng

QMS & Compliance Manager

2025-02-27