

Senbiosys SA  
Route des Gouttes-d'Or 40, 2000 Neuchâtel, Switzerland  
Tel: +41783060810  
Email: antonino.caizzone@senbiosys.com

---

Date: 09/11/2025

## FCC certification No. Cover Letter

We, **Senbiosys SA**, hereby submit justification for placing the FCC certification No. in the associated user's manual and packaging.

According to the FCC regulation, the FCC certification No. should be printed on the VELIA ring, but as the VELIA ring is too small to print the label (**FCC ID:2BKU5-SBDV0108**), it will be moved to the user's manual and packaging. The details are as below:

A. Side surface (A): The side surface does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



B. Top cover (B): The top cover does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.




Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the user's manual and packaging.

Senbiosys SA  
Route des Gouttes-d'Or 40, 2000 Neuchâtel, Switzerland  
Tel: +41783060810  
Email: antonino.caizzone@senbiosys.com

---

Label and Label location:



Best regards,

Signature: 

Print Name: Mr Antonino Caizzone  
Title: Chief Engineering & Operations Officer