



1. Outside view (单位:mm)



2.Wiring diagram:



- Process description :
- 1. The winding should be smooth, and the copper wire should not be crossed, knotted, or broken.
 - 2. Finished coat UL Heat shrink black sleeve.
 - 3. Cover the top with a rubber ring (as shown)

3. Test items:

31. Inductance:(1KHz, 0.25V)
L (S-F): 160uH±10%
2. DCR(@25℃)
R(S-F): Ω MAX

4. Insulation resistance: (AC 50/60Hz)
DC500V 100MΩ MIN PRI TO SEC WINDING-CORE

5. 材料明细:

NO.	Material Name	Material/ specifications	Supplier	UL No.
1	CORE	R10*35 磁棒	东磁	N/D
2	WIRE	2UEW 155℃	DONG GUAN YIDA INDUSTRIAL CO., LTD.	E344055
3	TUBE	UL TUBE	Dongguan Quantai Industrial Co., Ltd	E227336
4	SOLDER	LEADFREE Sn9. 7/0. 3Cu	Dongguan Xida Solder Products Co., Ltd	N/D
5	胶圈			
6				
7				

6. Antenna Gain
0dBi

	批准	审核	制订
		祖辉	