




























Freq. Stability 20C 138V ac20 5280MHz Ant1 0 Minutes




Freq. Stability -20C 120V ac20 5280MHz Ant1 0 Minutes







Freq. Stability -10C 120V ac20 5280MHz Ant1 0 Minutes




Freq. Stability 0C 120V ac20 5280MHz Ant1 0 Minutes








Freq. Stability 20C 102V ac20 5320MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:54:40

Freq. Stability 20C 120V ac20 5320MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:55:17

Freq. Stability 20C 138V ac20 5320MHz Ant1 0 Minutes





Date: 4.JUN.2025 13:54:51


Freq. Stability -20C 120V ac20 5320MHz Ant1 0 Minutes



Date: 4.JUN.2025 13:54:56




Freq. Stability 10C 120V ac20 5320MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:55:12

Freq. Stability 30C 120V ac20 5320MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:55:22

Freq. Stability 40C 120V ac20 5320MHz Ant1 0 Minutes





Date: 4.JUN.2025 13:55:27


Freq. Stability 50C 120V ac20 5320MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:55:33





Freq. Stability 20C 138V ac20 5500MHz Ant1 0 Minutes




Freq. Stability -20C 120V ac20 5500MHz Ant1 0 Minutes







Freq. Stability 10C 120V ac20 5500MHz Ant1 0 Minutes




Freq. Stability 30C 120V ac20 5500MHz Ant1 0 Minutes




Freq. Stability 40C 120V ac20 5500MHz Ant1 0 Minutes



Freq. Stability 50C 120V ac20 5500MHz Ant1 0 Minutes




Freq. Stability 20C 102V ac20 5600MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:01:32

Freq. Stability 20C 120V ac20 5600MHz Ant1 0 Minutes






Date: 4.JUN.2025 14:02:09



Freq. Stability 20C 138V ac20 5600MHz Ant1 0 Minutes




Freq. Stability -20C 120V ac20 5600MHz Ant1 0 Minutes









Freq. Stability 40C 120V ac20 5600MHz Ant1 0 Minutes



Freq. Stability 50C 120V ac20 5600MHz Ant1 0 Minutes




Freq. Stability 20C 102V ac20 5700MHz Ant1 0 Minutes







Date: 4.JUN.2025 14:05:16



Freq. Stability 20C 120V ac20 5700MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:05:52












Freq. Stability 40C 120V ac20 5700MHz Ant1 0 Minutes







Freq. Stability 50C 120V ac20 5700MHz Ant1 0 Minutes













Freq. Stability 40C 120V ac20 5745MHz Ant1 0 Minutes



Date: 4.JUN.2025 14:09:29

Freq. Stability 50C 120V ac20 5745MHz Ant1 0 Minutes



Date: 4.JUN.2025 14:09:35