








EUT INTERNAL PHOTOGRAPHS



















Bluetooth function of this chip
was disabled by manufacturer

Antenna