







Band2_3MHz_16QAM_18615_1RB#14_1000~3000_1000~30
00




Band2_3MHz_16QAM_18615_1RB#14_3000~20000_3000~2
0000



Band2_3MHz_QPSK_18615_15RB#0_0.009~0.15_0.009~0.1
5




Band2_3MHz_QPSK_18615_15RB#0_0.15~30_0.15~30



22:09:00 08.01.2024


Band2_3MHz_QPSK_18615_15RB#0_30~1000_30~1000



22:09:12 08.01.2024


Band2_3MHz_QPSK_18615_15RB#0_1000~3000_1000~300

0



22:09:24 08.01.2024


Band2_3MHz_QPSK_18615_15RB#0_3000~20000_3000~20000



22:09:30 08.01.2024


Band2_3MHz_16QAM_18615_15RB#0_0.009~0.15_0.009~0.15

15




22:09:34 08.01.2024

Band2_3MHz_16QAM_18615_15RB#0_0.15~30_0.15~30




22:09:39 08.01.2024

Band2_3MHz_16QAM_18615_15RB#0_30~1000_30~1000




22:09:51 08.01.2024

Band2_3MHz_16QAM_18615_15RB#0_1000~3000_1000~30
00




22:10:03 08.01.2024


Band2_3MHz_16QAM_18615_15RB#0_3000~20000_3000~2
0000




Band2_3MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15




Band2_3MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_3MHz_QPSK_18900_1RB#0_30~1000_30~1000




Band2_3MHz_QPSK_18900_1RB#0_1000~3000_1000~3000




Band2_3MHz_QPSK_18900_1RB#0_3000~20000_3000~20000




Band2_3MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.15



Band2_3MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




Band2_3MHz_16QAM_18900_1RB#0_30~1000_30~1000



22:11:15 08.01.2024

Band2_3MHz_16QAM_18900_1RB#0_1000~3000_1000~300


0



22:11:27 08.01.2024

Band2_3MHz_16QAM_18900_1RB#0_3000~20000_3000~20


000



22:11:34 08.01.2024


Band2_3MHz_QPSK_18900_1RB#14_0.009~0.15_0.009~0.1

5




22:11:38 08.01.2024

Band2_3MHz_QPSK_18900_1RB#14_0.15~30_0.15~30



22:11:43 08.01.2024


Band2_3MHz_QPSK_18900_1RB#14_30~1000_30~1000



22:11:55 08.01.2024

Band2_3MHz_QPSK_18900_1RB#14_1000~3000_1000~300


0



22:12:06 08.01.2024

Band2_3MHz_QPSK_18900_1RB#14_3000~20000_3000~20


000




22:12:13 08.01.2024

Band2_3MHz_16QAM_18900_1RB#14_0.009~0.15_0.009~0.


15




Band2_3MHz_16QAM_18900_1RB#14_0.15~30_0.15~30




Band2_3MHz_16QAM_18900_1RB#14_30~1000_30~1000



Band2_3MHz_16QAM_18900_1RB#14_1000~3000_1000~30
00




Band2_3MHz_16QAM_18900_1RB#14_3000~20000_3000~2
0000




Band2_3MHz_QPSK_18900_15RB#0_0.009~0.15_0.009~0.1


5



Band2_3MHz_QPSK_18900_15RB#0_0.15~30_0.15~30




Band2_3MHz_QPSK_18900_15RB#0_30~1000_30~1000




Band2_3MHz_QPSK_18900_15RB#0_1000~3000_1000~300


0




Band2_3MHz_QPSK_18900_15RB#0_3000~20000_3000~20000




Band2_3MHz_16QAM_18900_15RB#0_0.009~0.15_0.009~0.15



Band2_3MHz_16QAM_18900_15RB#0_0.15~30_0.15~30




Band2_3MHz_16QAM_18900_15RB#0_30~1000_30~1000




22:13:52 08.01.2024

Band2_3MHz_16QAM_18900_15RB#0_1000~3000_1000~3000




22:14:04 08.01.2024

Band2_3MHz_16QAM_18900_15RB#0_3000~20000_3000~20000




22:14:16 08.01.2024

Band2_3MHz_QPSK_19185_1RB#0_0.009~0.15_0.009~0.15




22:14:20 08.01.2024


Band2_3MHz_QPSK_19185_1RB#0_0.15~30_0.15~30




Band2_3MHz_QPSK_19185_1RB#0_30~1000_30~1000




Band2_3MHz_QPSK_19185_1RB#0_1000~3000_1000~3000



Band2_3MHz_QPSK_19185_1RB#0_3000~20000_3000~2000
00




Band2_3MHz_16QAM_19185_1RB#0_0.009~0.15_0.009~0.1
5




22:15:00 08.01.2024

Band2_3MHz_16QAM_19185_1RB#0_0.15~30_0.15~30



22:15:05 08.01.2024


Band2_3MHz_16QAM_19185_1RB#0_30~1000_30~1000



22:15:16 08.01.2024

Band2_3MHz_16QAM_19185_1RB#0_1000~3000_1000~300


0



22:15:28 08.01.2024


Band2_3MHz_16QAM_19185_1RB#0_3000~20000_3000~20

000




Band2_3MHz_QPSK_19185_1RB#14_0.009~0.15_0.009~0.1


5



Band2_3MHz_QPSK_19185_1RB#14_0.15~30_0.15~30




Band2_3MHz_QPSK_19185_1RB#14_30~1000_30~1000




Band2_3MHz_QPSK_19185_1RB#14_1000~3000_1000~300

0




22:16:08 08.01.2024

Band2_3MHz_QPSK_19185_1RB#14_3000~20000_3000~20000




22:16:14 08.01.2024

Band2_3MHz_16QAM_19185_1RB#14_0.009~0.15_0.009~0.15




22:16:19 08.01.2024

Band2_3MHz_16QAM_19185_1RB#14_0.15~30_0.15~30




22:16:23 08.01.2024


Band2_3MHz_16QAM_19185_1RB#14_30~1000_30~1000




Band2_3MHz_16QAM_19185_1RB#14_1000~3000_1000~30
00




Band2_3MHz_16QAM_19185_1RB#14_3000~20000_3000~2
0000




Band2_3MHz_QPSK_19185_15RB#0_0.009~0.15_0.009~0.1
5




Band2_3MHz_QPSK_19185_15RB#0_0.15~30_0.15~30




Band2_3MHz_QPSK_19185_15RB#0_30~1000_30~1000




Band2_3MHz_QPSK_19185_15RB#0_1000~3000_1000~300
0




Band2_3MHz_QPSK_19185_15RB#0_3000~20000_3000~20
000




Band2_3MHz_16QAM_19185_15RB#0_0.009~0.15_0.009~0.
15




Band2_3MHz_16QAM_19185_15RB#0_0.15~30_0.15~30




Band2_3MHz_16QAM_19185_15RB#0_30~1000_30~1000




Band2_3MHz_16QAM_19185_15RB#0_1000~3000_1000~30
00




Band2_3MHz_16QAM_19185_15RB#0_3000~20000_3000~2
0000




Band2_5MHz_QPSK_18625_1RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_QPSK_18625_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_18625_1RB#0_30~1000_30~1000




Band2_5MHz_QPSK_18625_1RB#0_1000~3000_1000~3000




Band2_5MHz_QPSK_18625_1RB#0_3000~20000_3000~20000
00




Band2_5MHz_16QAM_18625_1RB#0_0.009~0.15_0.009~0.15
5



Band2_5MHz_16QAM_18625_1RB#0_0.15~30_0.15~30




Band2_5MHz_16QAM_18625_1RB#0_30~1000_30~1000




Band2_5MHz_16QAM_18625_1RB#0_1000~3000_1000~300

0




Band2_5MHz_16QAM_18625_1RB#0_3000~20000_3000~20000

000




Band2_5MHz_QPSK_18625_1RB#24_0.009~0.15_0.009~0.1

5




Band2_5MHz_QPSK_18625_1RB#24_0.15~30_0.15~30



22:19:53 08.01.2024


Band2_5MHz_QPSK_18625_1RB#24_30~1000_30~1000



22:20:05 08.01.2024

Band2_5MHz_QPSK_18625_1RB#24_1000~3000_1000~300


0



22:20:17 08.01.2024

Band2_5MHz_QPSK_18625_1RB#24_3000~20000_3000~20


000




22:20:23 08.01.2024

Band2_5MHz_16QAM_18625_1RB#24_0.009~0.15_0.009~0.


15




Band2_5MHz_16QAM_18625_1RB#24_0.15~30_0.15~30




Band2_5MHz_16QAM_18625_1RB#24_30~1000_30~1000



Band2_5MHz_16QAM_18625_1RB#24_1000~3000_1000~30
00




Band2_5MHz_16QAM_18625_1RB#24_3000~20000_3000~2
0000




Band2_5MHz_QPSK_18625_25RB#0_0.009~0.15_0.009~0.1


5



Band2_5MHz_QPSK_18625_25RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_18625_25RB#0_30~1000_30~1000




Band2_5MHz_QPSK_18625_25RB#0_1000~3000_1000~300

0




22:21:35 08.01.2024

Band2_5MHz_QPSK_18625_25RB#0_3000~20000_3000~20000




22:21:42 08.01.2024

Band2_5MHz_16QAM_18625_25RB#0_0.009~0.15_0.009~0.15




22:21:46 08.01.2024

Band2_5MHz_16QAM_18625_25RB#0_0.15~30_0.15~30




22:21:51 08.01.2024

Band2_5MHz_16QAM_18625_25RB#0_30~1000_30~1000




Band2_5MHz_16QAM_18625_25RB#0_1000~3000_1000~30

00




Band2_5MHz_16QAM_18625_25RB#0_3000~20000_3000~2


0000




Band2_5MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_18900_1RB#0_30~1000_30~1000




Band2_5MHz_QPSK_18900_1RB#0_1000~3000_1000~3000



Band2_5MHz_QPSK_18900_1RB#0_3000~20000_3000~20000




Band2_5MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.1




22:23:10 08.01.2024

Band2_5MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




22:23:15 08.01.2024

Band2_5MHz_16QAM_18900_1RB#0_30~1000_30~1000




22:23:26 08.01.2024

Band2_5MHz_16QAM_18900_1RB#0_1000~3000_1000~300
0




22:23:38 08.01.2024

Band2_5MHz_16QAM_18900_1RB#0_3000~20000_3000~20
000




Band2_5MHz_QPSK_18900_1RB#24_0.009~0.15_0.009~0.1


5



Band2_5MHz_QPSK_18900_1RB#24_0.15~30_0.15~30




Band2_5MHz_QPSK_18900_1RB#24_30~1000_30~1000




Band2_5MHz_QPSK_18900_1RB#24_1000~3000_1000~300

0




22:24:18 08.01.2024

Band2_5MHz_QPSK_18900_1RB#24_3000~20000_3000~20000




22:24:25 08.01.2024

Band2_5MHz_16QAM_18900_1RB#24_0.009~0.15_0.009~0.15



22:24:29 08.01.2024

Band2_5MHz_16QAM_18900_1RB#24_0.15~30_0.15~30



22:24:34 08.01.2024

Band2_5MHz_16QAM_18900_1RB#24_30~1000_30~1000