



Tx. Spurious NVNT ac20 5825MHz Ant1 Emission




Date: 4.SEP.2025 17:59:43

Tx. Spurious NVNT ac40 5755MHz Ant1 Emission




Date: 4.SEP.2025 18:13:50

Tx. Spurious NVNT ac40 5795MHz Ant1 Emission




Date: 4.SEP.2025 18:16:19

Tx. Spurious NVNT ax20 5745MHz Ant1 Emission




Date: 4.SEP.2025 18:48:38

Tx. Spurious NVNT ax20 5785MHz Ant1 Emission




Date: 4.SEP.2025 18:52:26

Tx. Spurious NVNT ax20 5825MHz Ant1 Emission




Date: 4.SEP.2025 18:57:11

Tx. Spurious NVNT ax40 5755MHz Ant1 Emission




Date: 4.SEP.2025 19:01:00

Tx. Spurious NVNT ax40 5795MHz Ant1 Emission




Date: 4.SEP.2025 19:04:20


Tx. Spurious NVNT n20 5745MHz Ant1 Emission



Tx. Spurious NVNT n20 5785MHz Ant1 Emission




Tx. Spurious NVNT n20 5825MHz Ant1 Emission




Date: 4.SEP.2025 17:50:38

Tx. Spurious NVNT n40 5755MHz Ant1 Emission



Date: 4.SEP.2025 18:08:39

Tx. Spurious NVNT n40 5795MHz Ant1 Emission



Date: 4.SEP.2025 18:11:16

5 Photos of EUT

Please refer to report A2508189-C04-R01.

-----END OF REPORT-----