



20MHz_High_16QAM_1@99




20MHz_High_16QAM_25@75




B66 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0



1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:08:55

1.4MHz_High_QPSK_6@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:09:18

1.4MHz_High_16QAM_1@5




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:09:42

1.4MHz_High_16QAM_6@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:10:05

3MHz_Low_QPSK_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:11:37

3MHz_Low_QPSK_15@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:12:03

3MHz_Low_16QAM_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:12:29

3MHz_Low_16QAM_15@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:12:55

3MHz_High_QPSK_1@14




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:13:27

3MHz_High_QPSK_15@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:13:52

3MHz_High_16QAM_1@14




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:14:18

3MHz_High_16QAM_15@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:14:43

5MHz_Low_QPSK_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:16:04

5MHz_Low_QPSK_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:16:28

5MHz_Low_16QAM_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:16:52

5MHz_Low_16QAM_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:17:15

5MHz_High_QPSK_1@24




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:17:47

5MHz_High_QPSK_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:18:11

5MHz_High_16QAM_1@24




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:18:37

5MHz_High_16QAM_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:19:01

10MHz_Low_QPSK_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:20:15

10MHz_Low_QPSK_50@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:20:49

10MHz_Low_16QAM_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:21:24

10MHz_Low_16QAM_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:21:59

10MHz_High_QPSK_1@49




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:22:44

10MHz_High_QPSK_50@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:23:19

10MHz_High_16QAM_1@49




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:23:55

10MHz_High_16QAM_25@25




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 14.JAN.2025 13:15:26

15MHz_Low_QPSK_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:25:26

15MHz_Low_QPSK_75@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:26:09

15MHz_Low_16QAM_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:26:53

15MHz_Low_16QAM_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:27:36

15MHz_High_QPSK_1@74




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:28:28

15MHz_High_QPSK_75@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:29:11

15MHz_High_16QAM_1@74




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:29:55

15MHz_High_16QAM_25@50




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 14.JAN.2025 16:04:51

20MHz_Low_QPSK_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:31:44

20MHz_Low_QPSK_100@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:32:40

20MHz_Low_16QAM_1@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:33:35

20MHz_Low_16QAM_25@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:34:30

20MHz_High_QPSK_1@99




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:35:41

20MHz_High_QPSK_100@0




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 13:37:21

20MHz_High_16QAM_1@99




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:38:17

20MHz_High_16QAM_25@75




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 14.JAN.2025 16:06:39


5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




5MHz_High_QPSK_1@0(30MHz~9.49GHz)




10MHz_Low_QPSK_1@0(30MHz~9.49GHz)



10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




10MHz_High_QPSK_1@0(30MHz~9.49GHz)




FCC Part 24E

B2 , Normal
 1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:25:32

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:25:53

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:26:14

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:28:12

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:28:56

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:29:39

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:31:53

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:32:35

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:33:17

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:35:24

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:36:09

20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 9.JAN.2025 18:36:54


FCC Part 27

B4 , Normal
 1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



10MHz_High_QPSK_1@0(30MHz~18.55GHz)




15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 9.JAN.2025 18:49:31

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 9.JAN.2025 18:50:11

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 9.JAN.2025 18:50:52

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 9.JAN.2025 18:53:19

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 9.JAN.2025 18:54:04


20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 9.JAN.2025 18:54:48

B7 , Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 09:14:26

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 09:15:11

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 09:15:57

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 09:17:10

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 09:17:57


20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
 Date: 10.JAN.2025 09:18:45

B66 , Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 13.JAN.2025 13:53:43

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:43:13

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:43:32

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:44:05

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:44:44

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:45:25

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:46:10

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:46:35

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:47:17

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:49:22

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:49:48

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402A69105E-RF Tester:Loge Long
Date: 10.JAN.2025 13:50:29

**** END ****