



5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:30:40

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:30:59

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:31:19

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:32:36

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:32:55

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:33:15

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:34:34

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:34:52

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:35:10

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:36:30

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:36:48

20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:37:06


LTE Band 25, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.15GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.15GHz)




3MHz_Low_QPSK_1@0(30MHz~20.15GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.15GHz)



3MHz_High_QPSK_1@0(30MHz~20.15GHz)




5MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:31:44

5MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:32:02

5MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:32:20

10MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:33:39

10MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:33:58

10MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:34:16

15MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:35:36

15MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:35:55

15MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:36:15

20MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:37:34

20MHz_Middle_QPSK_1@0(30MHz~20.15GHz)



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:37:54

20MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 18:38:14


FCC Part 27

LTE Band 4, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:36:41

10MHz Low QPSK 1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:10:49

10MHz High QPSK 1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:11:29

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:13:12

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:13:32

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:13:53

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:20:49

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:21:09

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:21:30

LTE Band 7, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:45:00

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:45:22

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:45:44

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:47:04

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:47:26

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:47:47


15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




15MHz_High_QPSK_1@0(30MHz~26.7GHz)




20MHz_Low_QPSK_1@0(30MHz~26.7GHz)



20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




20MHz_High_QPSK_1@0(30MHz~26.7GHz)



LTE Band 12, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:53:31

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:53:46

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:54:01

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:55:14

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:55:29

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:55:45

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:56:58

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:57:14

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 14.DEC.2024 00:57:29

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:33:17

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:33:34

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:33:51

LTE Band 13, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:44:43

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:44:52

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:45:02

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:45:26

5MHz_High_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:45:42

5MHz_High_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:45:53

5MHz_High_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:46:04

5MHz_High_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:47:24

10MHz_Middle_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:49:04

10MHz_Middle_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:49:15

10MHz_Middle_QPSK_1@0(793MHz~806MHz)



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:49:26

10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 15:49:58


LTE Band 17, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



10MHz_High_QPSK_1@0(30MHz~8.16GHz)



***** END *****