




Band 2, Normal**1RB was the worst case****1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)**


ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:28:29

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)


ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:28:51

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)


ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:29:13

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:30:56


3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:31:18

3MHz_High_QPSK_1@0(30MHz~20.1GHz)


ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:31:40

5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:33:13

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:33:36

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:33:58

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:34:49

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:35:34

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:36:19

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:37:35

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:38:21

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:39:07

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:41:07

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:41:55

20MHz_High_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:42:40

FCC Part 27

Band 4, Normal

Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-33.34	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-34.00	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)	-34.45	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-33.88	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-34.28	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~18.55GHz)	-33.58	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-34.54	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-34.08	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~18.55GHz)	-33.51	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-33.49	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-32.68	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~18.55GHz)	-33.96	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-34.32	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-33.43	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~18.55GHz)	-34.13	See Graphs	Pass
20MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-34.56	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-34.20	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~18.55GHz)	-33.94	See Graphs	Pass

Band 7, Normal

Mode	Value (dBm)	Limit	Verdict
5MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-33.80	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-33.89	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~26.7GHz)	-33.54	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-34.18	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-33.83	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~26.7GHz)	-33.59	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-34.62	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-34.25	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~26.7GHz)	-34.22	See Graphs	Pass

Mode	Value (dBm)	Limit	Verdict
20MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-34.00	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-34.05	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~26.7GHz)	-33.78	See Graphs	Pass

Band 66, Normal


Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-23.45	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-23.35	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)	-24.30	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-23.77	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-24.17	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~18.8GHz)	-23.20	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-23.90	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-23.03	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~18.8GHz)	-24.14	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-23.60	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-22.66	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~18.8GHz)	-23.80	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-23.27	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-23.61	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~18.8GHz)	-23.98	See Graphs	Pass
20MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-23.61	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-23.77	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~18.8GHz)	-24.11	See Graphs	Pass

Note:1RB was the worst case.

Band 4, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:45:23

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:45:45

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:46:07

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:47:41

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:48:03

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:48:25

5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:50:01

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:50:25

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:50:48

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:51:54

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:52:39

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:53:25

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:54:41

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:55:26

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:56:12

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:57:33

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:58:18

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:59:04

Band 7, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:14:25

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:14:51

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:15:14

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:16:27

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:17:18

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:18:08

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:20:01

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:20:49

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:21:38

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:23:46

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:24:34


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 5.APR.2025 18:25:21


1RB was the worst case

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 6.APR.2025 15:59:46

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 6.APR.2025 16:02:16

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 6.APR.2025 16:03:50

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 6.APR.2025 16:05:29

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)



Comment: ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 6.APR.2025 16:07:55

10MHz_High_QPSK_1@0(30MHz~18.8GHz)



Comment: ProjectNo.:2503R09084E-RF Tester:Chin Qin
Date: 6.APR.2025 16:11:12