




15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




15MHz_High_QPSK_1@0(30MHz~18.55GHz)




20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




20MHz_High_QPSK_1@0(30MHz~18.55GHz)




Band 7, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:29:14

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:30:35

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:31:52

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:33:59

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:36:34

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:39:10


15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




15MHz_High_QPSK_1@0(30MHz~26.7GHz)




20MHz_Low_QPSK_1@0(30MHz~26.7GHz)



20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




20MHz_High_QPSK_1@0(30MHz~26.7GHz)




Band 12 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:58:48

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:00:02

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:01:17

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:02:51

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:04:05

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:05:21


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




10MHz_High_QPSK_1@0(30MHz~8.16GHz)




Band 13 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:12:31

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:13:32

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:13:47

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:14:01

5MHz_High_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:14:28

5MHz_High_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:15:26


5MHz_High_QPSK_1@0(793MHz~806MHz)




5MHz_High_QPSK_1@0(1559MHz~1610MHz)




10MHz_Middle_QPSK_1@0(30MHz~8.87GHz)




10MHz_Middle_QPSK_1@0(763MHz~775MHz)



10MHz_Middle_QPSK_1@0(793MHz~806MHz)




10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)




Band 17 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:18:28

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:19:43

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:21:02

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:22:34

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:25:04


10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:27:35


Band 38 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:30:17

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:31:39

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:33:00

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:34:35

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:37:14

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 18:39:55


15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




15MHz_High_QPSK_1@0(30MHz~27.2GHz)




20MHz_Low_QPSK_1@0(30MHz~27.2GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




20MHz_High_QPSK_1@0(30MHz~27.2GHz)




Band 41 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 10:59:37

5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:00:57

5MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:02:20

10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:03:58

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:06:44

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:09:32


15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




15MHz_High_QPSK_1@0(30MHz~27.9GHz)




20MHz_Low_QPSK_1@0(30MHz~27.9GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




20MHz_High_QPSK_1@0(30MHz~27.9GHz)




Band 66 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:32:18

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:33:39

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:34:59

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:36:23

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:37:45

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:39:06

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:40:29

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:41:50

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:43:11

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:44:35

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:47:13

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:49:53

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:52:38

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:55:21

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 19:58:02

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 20:00:47

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 20:03:29

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 20:06:12

***** END *****