



LTE Band 2 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:54:35

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:55:24

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:56:03

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 11.MAY.2025 15:56:53

3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:57:24

3MHz_High_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:58:03

5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:58:46

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 21:59:25

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:00:05

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:00:48

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:01:27

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:02:07

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:02:50

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:03:29

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:04:09

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:04:52

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:05:37

20MHz_High_QPSK_1@0(30MHz~20.1GHz)



Comment: ProjectNo.:2503S14680E-RF Tester:Chin Qin
Date: 28.APR.2025 22:06:17

FCC Part 27**LTE Band 4 , Normal**

Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-18.61	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-18.93	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)	-19.08	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-19.34	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-19.29	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~18.55GHz)	-18.60	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-18.83	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-18.83	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~18.55GHz)	-18.79	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-18.71	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-17.83	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~18.55GHz)	-18.98	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-18.45	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-18.31	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~18.55GHz)	-18.54	See Graphs	Pass
20MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-17.84	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-18.74	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~18.55GHz)	-18.53	See Graphs	Pass

Note:1RB was the worst case.