



Emergent Solutions Inc.

Suite C107, 3600 Steeles Ave. E
Markham, ON, Canada L3R 9Z7
Main Phone: +1 (416) 618-2100
email: info@emergent-sol.com
WEB Site: www.emergent-sol.com

Nemko North America, Inc.
303 River Road, Ottawa, Ontario, Canada K1V 1H2
Attn: Director of Certification

Tune-Up Procedure for Licensed Transmitter

FCC ID: 2BOHX-EBR100MODX
IC: 33834-EBR100MODX
Model (HVIN): EBR100MODX

Dear Director of Certification,

Note: End users are not required to perform any additional tune-up procedures. All required tune-ups and measurements are performed at the factory during production. The products are factory calibrated to 0.126 W (21 dBm \pm 0.5 dB) carrier power at the antenna connector.

Statement:

The product does not contain transmission components that are user-tunable. As a result, there is no need for end users to perform any tune-up procedures for operation. Therefore, no specific tune-up instructions are provided in this document.

Sincerely,

Dated: July 30, 2025

Signed by:

A handwritten signature in black ink that reads 'Rodney Cronin'.

Signature

Rodney Cronin

Print name

VP Products and System Integration

Title

(416) 618-4350

Phone

On behalf of:

Emergent Solutions Inc.

Company name