

**Due Diligence Letter**  
For Certification Service in the USA

**Federal Communications Commission**  
Equipment Authorization Division, Application Processing Branch  
7435 Oakland Mills Road  
**Columbia, MD 21048**

To whom it may concern

FCC ID	Model name
2BQIK-TX8	TX8, Tanix TX1, TX1

Pursuant to KDB 986446 D01 Covered Equipment Guidance the evaluation of the product above shows compliance for the following reasons:

Compliance	Evaluation process		Results
Inherent compliance	<input checked="" type="checkbox"/>	The chipset(s) used is not capable of running the cybersecurity and/or anti-virus software	Compliance
	<input checked="" type="checkbox"/>	The memory used does not allow the running the cybersecurity and/or anti-virus software	Compliance
	<input checked="" type="checkbox"/>	The storage capacity does not allow the running the cybersecurity and/or anti-virus software	Compliance
	<input checked="" type="checkbox"/>	The operating system used is not capable of running the cybersecurity and/or anti-virus software	Compliance
No inherent compliance	<input type="checkbox"/>	Based on software bill of material	Compliance
	<input type="checkbox"/>	Based on scan for running software on the device	
	<input type="checkbox"/>	Based on filesystem scan for cybersecurity and/or anti-virus software	

The equipment for which authorization is sought complies with the rules and fulfils the requirements as detailed in the above mentioned KDB.

**Evaluation performed by**

Company Name: MAXLAB Testing Co., Ltd.

Contact Name: Harry Chen

Address: 1/F, Building B, Xinshidai GR Park, Shiyan Street, Bao'an District, Shenzhen, Guangdong, 518052, People's Republic of China

Phone: +86-15691418608

Email: [harry@att-lab.cn](mailto:harry@att-lab.cn)

Signature: 

Date: 2025-06-24