

INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)



FCC ID: A2HPA5075U-1SPA
IC: 9903A-PA5075U1SPA



INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12061489-1

Equipment Photographs

Model: PA5075U-1SPA

(Internal)

