



INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87


INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87



INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87


INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87


INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87



INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87


INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87



INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87