



# Intertek Testing Services

Radio Shack, A Division of Tandy Corporation, Scanning Receiver    Date of Test: July 20 & 23, 1998  
FCC ID: AAO2000312

## 3.2 Radiated Emission Configuration Photograph

Worst Case Radiated Emission  
at 50.2 MHz



# Intertek Testing Services

Radio Shack, A Division of Tandy Corporation, Scanning Receiver      Date of Test: July 20 & 23, 1998  
FCC ID: AAO2000312

## 3.4 AC conducted Emission Configuration Photograph

Worst Case Conducted Emission  
at 0.6011 MHz

