



Intertek Testing Services

Radio Shack, A Division of Tandy Corporation, Scanning Receiver
FCC ID: AAO2000421

Date of Test: August 7, 1998

3.2 Radiated Emission Configuration Photograph

Worst Case Radiated Emission
at 143.1 MHz



Intertek Testing Services

Radio Shack, A Division of Tandy Corporation, Scanning Receiver
FCC ID: AAO2000421

Date of Test: August 7, 1998

3.4 AC conducted Emission Configuration Photograph

Worst Case Conducted Emission
at 20.74 MHz

