
INTERTEK TESTING SERVICES

C. Test Result

Table 6(a)

**RadioShack, A Division of Tandy Corporation
RadioShack 21-1803**

Frequency Deviation with Temperature Variation

Channel : 1

Temperature (°C)	Assigned Frequency (MHz)	Measured Frequency (MHz)	% Deviation
-20	462.5625	No transmission	No transmission
-10	462.5625	No transmission	No transmission
0	462.5625	462.562701	0.000043
10	462.5625	462.562522	0.000005
20	462.5625	462.562348	-0.000033
30	462.5625	462.562160	-0.000074
40	462.5625	462.561920	-0.000125
50	462.5625	462.561750	-0.000162

Test Engineer: Wilson S. K. Loke

Date of Test: August 24, 1998