



INTERTEK TESTING SERVICE

Report No.: HK09080476-1



Equipment Photographs Model : 33-282 (TX) (Internal)



INTERTEK TESTING SERVICE

Report No.: HK09080476-1

Equipment Photographs Model : 33-282 (TX) (Internal)



INTERTEK TESTING SERVICE

Report No.: HK09080476-1

Equipment Photographs Model : 33-282 (TX) (Internal)



INTERTEK TESTING SERVICE

Report No.: HK09080476-1

Equipment Photographs
Model : 33-282 (TX)
(Internal)

