

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

**Module(Horizontal: X-axis/ Vertical:X-axis)
Antenna(Horizontal: Y-axis/ Vertical:Y-axis)**


Module X-axis




Antenna X-axis




Module Y-axis



Antenna Y-axis



Module Z-axis



Antenna Y-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124