

Ritron, Incorporated 505 W. Carmel Drive · Carmel, IN 46032 P. O. Box 1998 · Carmel, IN 46082 Ph: 317-846-1201 Fax: 317-846-4978

Email: ritron@ritron.com Web Site: www.ritron.com

March 29, 2019

Timco Engineering, Inc. 849 NW State Road 45 P.O. Box 370 Newberry, Florida 32669

Re: FCC ID Change

To Whom It May Concern,

Pursuant of FCC Part 2.933 (b), Ritron, Inc. requests a change in the identification of the following Type Accepted equipment.

 Original ID
 Original Grant
 Requested ID Change

 R72NEP100
 05/03/2016
 AIERIT48-174

 R72NEP400
 05/03/2016
 AIERIT48-470

The differences between the equipment with the original identification and the equipment with the identification change are:

- 1. The original manufacturer model name and number will be replaced with the Ritron model name and number.
- 2. Any label with reference to the original manufacturer will be replaced with the Ritron name.
- 3. There will be no mechanical or electrical changes made to the original equipment. Therefore, all original test results will continue to be representative of and applicable to the equipment.

The following documents are included with the request of identification change:

- 1. Photographs required by FCC Part 2.1033 (b)(7) or (c)(12) showing the exterior appearance of the equipment and the operating controls available to the user.
- 2. Drawings of the new FCC ID label.
- 3. Completed FCC Form 731 for each request of identification change.
- 4. Permission Letter from original manufacturer.

Regards,

Kevin G. Matson Senior Project Manager

Kevin D. Matson

RITRON, Inc.

kmatson@ritron.com