

Bluetooth Chip

Storage area of software will be changed from external Flash to internal mask ROM.

Regarding RF parts, there's no modification because the silicon is the same.

And there's also no modification of Bluetooth identifier.

