

Uniden America Corporation  
301 International Pkwy Suite 460  
Flower Mound, TX 75022  
817-858-3300

---

**Uniden**

June 11, 2025

**To:** Federal Communications Commission Equipment Authorization Branch Laboratory Division  
Office of Engineering and Technology 7435 Oakland Mills Road  
Columbia, Maryland 21046

**Subject:** Attestation statement regarding the WARNING: MODIFICATION label located inside the battery compartment

**TYPE OF EQUIPMENT:** Scanning Receiver


**FCC IDENTIFIER:** AMWUB391

I attest that the SDS150 Battery Pack will be shipped in the packaging separately from the receiver and must be installed prior to scanner operations. The "WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE SERVICE IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW" is visible to the consumer prior to installation of the battery pack. There is also a statement located in the Owner's Manual, Page 2, "IMPORTANT!".

There is no adequate location on the exterior of the product where the label would last the life of the product and therefore would not be a practical location.

Please contact the undersigned if you have any questions or need any further information.

Regards,



Paul Roby  
Regulatory and Quality Manager