

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS

External Photographs




Figure 1. EUT Front

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS



Figure 2. EUT Right Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS




Figure 3. EUT Back

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS




Figure 4. EUT Left Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS




Figure 5. EUT Top Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS



Figure 6. EUT Bottom Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0183
24-0408
February 10, 2025
Sharp Corporation
SWA3099MS




Figure 6. EUT Internal Chamber