

Sharp Corporation , FCC ID: APYHRO00066, Assessment NO.: AN08T7846, Notice#1

Inbox
X

Priority
X

 from **tim.dwyer@ccsemc.com**
to spetrusk@sharpsec.com,
cc tim.dwyer@ccsemc.com,
date Wed, Apr 23, 2008 at 1:58 PM
subject Sharp Corporation , FCC ID: APYHRO00066, Assessment NO.: AN08T7846, Notice#1

[hide details](#) Apr 23 (2 days ago)

 [Reply](#)

Hello Steve,

Review of this application is complete. Aside from two minor administrative issues all is ok. Please reply to the following items so that we can continue and issue the grant.

Q1. The emission designator in application and in the Part 22 report is 4M119W. It appears that this is a typographical error and that it should be 4M11F9W. Please reply with revised report or with email correction statement so that we can enter the change in the application form.

Q2. SAR values are not included on page 517 of user manual. Placeholders (\$\$) are used. Please provide revised page 517. The revised manual will also be attached to the two other composite applications.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer
Technical Reviewer

 [Reply](#)  [Reply to all](#)  [Forward](#)

 from **Petruska, Steve** <spetrusk@sharpsec.com>
to tim.dwyer@ccsemc.com,
date Thu, Apr 24, 2008 at 11:24 AM
subject RE: Sharp Corporation , FCC ID: APYHRO00066, Assessment NO.: AN08T7846, Notice#1

[hide details](#) 11:24 AM (5 hours ago)

 [Reply](#)

Hi Tim,

Thank you for your review. Below is our response for each of the comment items.

Q1. We confirm that the correct emission designator for the Part 22 documentation is "4M11F9W". "4M119W" was indicated in error. Please revise the application material accordingly.

Q2. Attached is a revised page 517 of the user manual with the SAR values included.

Best regards,

Steve Petruska
Sharp Electronics Corp.
201-529-9689
[- Show quoted text -](#)



SH906i manual P515-P517 revised.pdf

154K [View as HTML](#) [Download](#)