

WARNING Carbon Monoxide cannot be seen or smelled. If alarm signal sounds, 1) Operate HUSH button 2) Call your emergency services (Fire dept or 911. 3) Immediately move to fresh air-outdoors or by an open door or window

L00-0401-000

Honeywell

Smoke and Carbon
Monoxide Detector
Model No W4-IC

IC ID: XXXXXXXXX

FCC ID: AUBW4ICCOMBO

Photoelectric Smoke Detector
Principle and 85DB Sounder
Factory Sens: .9 to 2.84/FT
Carbon Monoxide Detection
Install/Operating Temp. Range
32° to 100° F (0 to 38° C)

DATE CODE: ????

For repair send to:
Honeywell
12220 Rojas Drive
Suite 700
El Paso, TX 79936
www.security.honeywell.com

MADE IN MEXICO



ZID: XXXXXXXXXXXXXXXXX



REPLACE BY: Sep/2026

See I56-5942-000 for installation,
maintenance and detector ratings

WARNING: Use only
Duracell DL123A or Panasonic CR123A.
Lithium Batteries may present risk
of fire or explosion. Remove all old
batteries, wait 10 seconds, then insert
four new batteries. Constant exposures
to high humidity may reduce battery life.
See the owner's manual for
safety precautions.

PATENT: www.firepat.net N04-0100-002



WARNING Carbon Monoxide cannot be seen or smelled. If alarm signal sounds, 1) Operate HUSH button 2) Call your emergency services (Fire dept or 911. 3) Immediately move to fresh air-outdoors or by an open door or window

L00-0401-000

Honeywell

Smoke and Carbon
Monoxide Detector
Model No W4-IC

IC ID: XXXXXXXXX

FCC ID: AUBW4ICCOMBO

Photoelectric Smoke Detector
Principle and 85DB Sounder
Factory Sens: .9 to 2.84/FT
Carbon Monoxide Detection
Install/Operating Temp. Range
32° to 100° F (0 to 38° C)

DATE CODE: ????

For repair send to:

Honeywell
12220 Rojas Drive
Suite 700
El Paso, TX 79936
www.security.honeywell.com

MADE IN MEXICO



ZID: XXXXXXXXXXXXXXXXX



REPLACE BY: Sep/2026

See I56-5942-000 for installation,
maintenance and detector ratings

WARNING: Use only
Duracell DL123A or Panasonic CR123A.
Lithium Batteries may present risk
of fire or explosion. Remove all old
batteries, wait 10 seconds, then insert
four new batteries. Constant exposures
to high humidity may reduce battery life.
See the owner's manual for
safety precautions.

PATENT: www.firepat.net N04-0100-002





