



Date: 26<sup>th</sup>July 2005

Bruno Clavier  
TIMCO Engineering Inc  
849 NW State Road 45  
Newberry, Florida 32669

REFERENCE: JOB 1550UC5 with FCC ID: AZ489FT5824.

Dear Mr. Clavier;

Motorola Inc., 8000 West Sunrise Boulevard, Fort Lauderdale, Florida 33322, herein submits its response to the 26th July 2005 request for information in JOB 1550UC5.

Q1. It could not be identified the location of the final probe rotation for the worst-case configuration. Please provide such information. Alternatively, please point out location in filing documents.

R1. The rotation was performed at the highest location for every configuration.

Contact me at (954) 723-5793 if you require any additional information.

Sincerely,

*/s/ Mike Ramnath (signed)*

Manager, Regulatory Compliance

Email: [Mike.Ramnath@motorola.com](mailto:Mike.Ramnath@motorola.com)