

**Exhibit 7B MPE Test Report Photographs****Motorola Solutions Inc.****EME Test Laboratory**

Motorola Solutions Malaysia Sdn Bhd (Innoplex)
Plot 2A, Medan Bayan Lepas,
Mukim 12 SWD 11900 Bayan Lepas Penang, Malaysia.

**Radio and Control Head***Tiong*

Tiong Nguk Ing
Deputy Technical Manager
Approval Date: 11/1/2016

Document Revision History

Date	Revision	Comments
11/1/2016	A	Initial release

1.0 Antenna Photograph(s)



VHF Antenna kit numbers, from left to right;
AN000197A01 (HAD4023A), AN000197A02 (HAD4024A), AN000197A03 (HAD4025A) and
AN000197A04 (HAD4026A)



UHF Antenna kit numbers, from left to right;
AN000197A05 (HAE6014A), AN000197A06 (HAE6032A), AN000197A07 (HAE6033A),
AN000197A08 (HAE6034A) and AN000197A09 (HAD4026A)



**7/800 Antenna kit numbers, from left to right;
AN000197A10 (HAF4015A) and AN000197A11 (HAF4018A)**

2.0 Test Measurement Setup Photos



Test measurement setup for Bystander



Test measurement setup for Operator