

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000

INTERNAL PHOTOGRAPHS



Figure 1. TR-6000 with Top Cover Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000



Figure 2. TR-6000, Face Plate PCB View

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000



Figure 3. TR-6000 Main PCB Side 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000



Figure 4. TR-6000 Main PCB Side 2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000



Figure 5. Filter #1 (Active) Top Cover Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000



Figure 6. Filter #1 (Active) Main PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

Part 90.242
B7MTR-6000TIS-WB
15-0297
February 4, 2015
RADIO SYSTEMS INC
TR-6000




Figure 7. Filter #2 (Passive) with Bottom Cover Removed