



Federal Communications Commission
7435 Oakland Mills Road
Columbia, Maryland 21046
USA

Date: December 22, 2021

Re: Change of Identification Authorization

To Whom It May Concern:

The purpose of this letter is to apply for a change in identification as specified under 47CFR2.933 of the FCC rules, based on the original FCC ID: RAS-MT7922A22M, grant date: 07/08/2021 and 09/27/2021

1. The equipment bearing the modified FCC ID: B94-MT7922A22MB is electrically identical to original equipment, there is no change in design, circuitry or construction.
2. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
3. The original software security exhibit showing this device meets the requirements of KDB 594280 continue to be representative of and applicable to the equipment bearing the changed identification.
4. As new grantee, we, HP Inc., responsible for changes to the device and will not alter or offer any capabilities that will modify DFS settings.
5. Grant line entry reduction: Requesting grant line entries be reduced, all frequencies are the same as the original grant, just reduced in accordance with KDB634817.

Sincerely,

Liang Rong Chiao

Liang Rong Chiao
Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan
frances.liang@hp.com
T : +886 2 3789-2469