



Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, Maryland 21046  
USA

Date: November 16, 2022

Re: Change of Identification Authorization

To Whom It May Concern:

The purpose of this letter is to apply for a change in identification as specified under 47CFR2.933 of the FCC rules, based on the original **FCC ID: TX2-RTL8852CE**, **grant date: 2022/11/21**

1. The equipment bearing the modified FCC ID: B94-RTL8852CEB is electrically identical to original equipment, there is no change in design, circuitry or construction.
2. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
3. The original software security exhibit showing this device meets the requirements of KDB 594280 continue to be representative of and applicable to the equipment bearing the changed identification.
4. As new grantee, we, HP Inc., responsible for changes to the device and will not alter or offer any capabilities that will modify DFS settings.

Sincerely,

A handwritten signature in black ink that reads 'Liang Rong Chiao'. The signature is written in a cursive style and is positioned above a horizontal line.

Liang Rong Chiao  
Worldwide Technical Regulations  
HP International Pte. Ltd., Taiwan Branch  
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan  
frances.liang@hp.com  
T : +886 2 3789-2469