



3390 East Harmony Road  
Fort Collins  
Colorado 80528  
United States

FCC Laboratory  
7435 Oakland Mills Rd.  
Columbia, MD 21046

To whom it may concern:

This device with FCC ID: B94HCI001PSR integrates a WWAN module:

	FCC ID	Grant Date
LTE Module	2AX2URW101RGL	08/27/2024

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D02 v02r02, the original modular report as following are submitted to represent the compliance of Part 22/24/27/90/96 conducted RF testing items of this device.

Report Number		
SZCR240700251802	SZCR240700251804	

The radiated RF testing items are tested on this host device, and the test report is submitted additionally.

Sincerely,

**Liang Rong Chiao**

Worldwide Technical Regulations

HP International Pte. Ltd., Taiwan Branch

10F-1, No. 66, Jingmao 2nd Road, Nangang District, Taipei 11568. Taiwan

frances.liang@hp.com

T +886-2-37892469