



Date: November 19, 2014

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: B94HHC408M

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: B94HHC408M to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,

A handwritten signature in black ink, appearing to read 'Chiahong Lin', written over a horizontal line.

Chiahong Lin
Chiahong_lin@compal.com