

3390 East Harmony Road
Fort Collins
Colorado 80528
United States



FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

To whom it may concern:

This device with FCC ID: **B94HNI61KLR** integrates a WWAN module:

	FCC ID	Grant Date
5G Module	2AX2URW350RGL	06/20/2024

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D02v01, the original modular report as following are submitted to represent the compliance of Part 22/24/27/90/96 conducted RF testing items of this device.

Report Number		
FG430728A	FG430728B	FG430728C
FG430728D	FG430728E	FG430728F
FG430728G	FG430728H	FG430728I
FG430728J	FG430728K	FG430728L
FG430728M	FG430728N	FG430728O
FG430728P	FG430728Q	FG430728R
FG430728S	FG430728T	FG430728U

The radiated RF testing items are tested on this host device, and the test report is submitted additionally.

Sincerely,

A handwritten signature in black ink that reads 'Liang Rong Chiao'.

Liang Rong Chiao

Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, No. 66, Jingmao 2nd Road, Nangang District, Taipei 11568. Taiwan
frances.liang@hp.com
T +886-2-37892469